

MERLIN[®]

CONTAMINATIONS CONTROLS SOLUTIONS



FILTERMAG[®]

Catalogue 2015

Merlin Equipment Pte Ltd
40 Tech Park Crescent, Singapore 638097
Tel: +65 6863 1753 Fax: +65 6863 1757
Email: sales@merlinequip.com



CT 4.9 Installed



Installation on :

- Fuel Filter
- Oil Filter
- Separator Fuel Filter.

CT 4.9 Installed



CT 4.9 Installed





Merlin Equipment Pte Ltd
40 Tech Park Crescent, Singapore 638097
Tel: +65 6863 1753 Fax: +65 6863 1757
Email: sales@merlinequip.com



CT 3.2 Installed



CT 3.8 Installed






CT 4.9 Installed




CT 4.9 Installed



Results Filter Cut



CT 4.9 Installed on Filters



Results Filter Cut



**Filter Cut Open To Investigate Amount Of Particle
Attracted To The CT4.9.**





Left and Right Hand Side Filters Installed with CT 3.8.



Results Filter Cut



Merlin Equipment Pte Ltd
40 Tech Park Crescent, Singapore 638097
Tel: +65 6863 1753 Fax: +65 6863 1757
Email: sales@merlinequip.com

Results Filter Cut



Hydraulic Application



Merlin Equipment Pte Ltd
40 Tech Park Crescent, Singapore 638097
Tel: +65 6863 1753 Fax: +65 6863 1757
Email: sales@merlinequip.com

Hydraulic Application



The R994 has three CT 4.9 installed onto the spin filters. It is encourage to double clamp filters.



The DR9 has two CT 4.9 installed onto the spin filters. It is encouraged to double clamp filters.




Merlin Equipment Pte Ltd
40 Tech Park Crescent, Singapore 638097
Tel: +65 6863 1753 Fax: +65 6863 1757
Email: sales@merlinequip.com



XT 7.0 are used on filters with thicker walls.

Merlin Equipment Pte Ltd
40 Tech Park Crescent, Singapore 638097
Tel: +65 6863 1753 Fax: +65 6863 1757
Email: sales@merlinequip.com



In this situation, the CT4.9 was able to prevent rust particles flowing through the fuel filters on a large haul truck.

